Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513	
Inspection Date(s): 10/16/2012, 10/17/2012, 10/18/2012, 10/19/2012 Man		
Inspection Unit: Springfield	·	
Location of Audit: Springfield		
Exit Meeting Contact: Mark Mancewicz		
Inspection Type: Standard Inspection - Field Audit		
Pipeline Safety Representative(s): Charles Gribbins		
Company Representative to Receive Report: Michael Fuller		
Company Representative's Email Address: mfuller2@ameren.com		

Headquarters Address Information:	eadquarters Address Information: 300 Liberty	
	Peoria, IL 61602	
	Emergency Phone#:	
	Fax#:	
Official or Mayor's Name:	Ron Pate	
	Phone#: (217) 424-6518	
	Email:	
Inspection Contact(s)	Title	Phone No.
Dallas Jett	Superintendent Quality Assurance	
Robert Roth	Senior Quality Assurance Consultant	
Mark Mancewicz	Superintendent Gas Operations	
Mike Fuller	Associate Engineer	

CRITERIA FOR AREA SELECTED	Status
Select from the criteria listed below when choosing a location to audit.	
General Comment:	
See information below for criteria related to Comprehensive Field Audit.	
Higher population density	No
General Comment:	
Population density was not a factor when the three different areas were picked.	

Age of system		Yes
General Comme	<u>nt:</u>	
Age of the system	n was a factor why staff selected coupled steel areas to conduct the inspection	
Type of piping		Yes
General Comme	<u>nt:</u>	
Type of piping wa	is coupled steel.	
Operating cha	racteristics	Yes
General Comme	<u>nt:</u>	
Medium pressure	area 20 to 30 pounds.	
Performance I	nistory of system	Yes
Manageable s	ized area should be chosen	No
General Comme	nt:	•
Staff chose three	small areas of the coupled steel systems.	
	MAPS OF FACILITIES INSPECTED	Status
192.605(b)(3)	Were system maps provided as part of this audit?	Yes
General Comme	<u>nt:</u>	
The operator pro	vided maps for each of the areas inspected.	
192.603(b)	Were system mapping used during this audit up to date?	Satisfactory
General Comme	<u>nt:</u>	
The maps were u	sed for a guide they had enough detail and also included address for the structures inspected.	
	CUSTOMER METER & REGULATOR	Status
Category Comm	ent:	
Grand Valley Tra. Lot #61 Lot #60 meter loc Lot #59 Lot #58 Lot #57 atmosphe Lot #56 meter loc Lot #55 meter loc Lot #54 meter loc Lot #53 Riser ber	ked off eric corrosion on service head adapter ked off ked off ked off ked off tracer wire missing out me painting surface rust racer wire inting	

Lot #26 meter lock Lot #25 meter lock Lot #24 meter lock Lot #23 Meter lock Lot #22 Meter lock Lot #21 Meter lock Lot #20 needs paid Lot #19 some corr Lot #18 Lot #17 Lot #16 needs som Lot #15 wire dama Lot #15 wire dama Lot #14 bad wire Lot #13 See cathodic protes	ted off sed of	
192.357(a)	Is the customer meter and regulator installed to minimize anticipated stresses upon connecting piping?	Satisfactory
General Commer	<u>nt:</u>	
Staff inspected the	above list meter sets and it did not appear that there were any issues with stresses on the connecting piping.	
192.353(a)	Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated?	Satisfactory
General Commer	<u>tt:</u>	
Staff inspected me to the resident.	eter locations listed in this checklist were found to be in accessible locations and were protected from vehicular dan	nage by placing them close
192.355(b)(1)	Is the customer regulator vent rain and insect resistant?	Satisfactory
General Commer	<u></u>	
The vent screens	were inspected on the customer meters listed in the checklist and all were found to rain and insect resistant.	
192.355(b)(2)	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Satisfactory
General Commer	<u>ıt:</u>	
All meter set locati	ions inspected were located where gas could vent freely into the atmosphere and away from building openings.	
192.355(b)(3)	Is the vent protected from damage caused by submergence in areas of flooding?	Satisfactory
General Commer	<u>tt:</u>	
The operators did	not have any meters that were located in any areas prone to flooding.	
192.357(d)	Is a customer regulator that might release gas vented to the outside atmosphere?	Satisfactory
General Commer	<u>ıt:</u>	
Of the entire mete	r sets inspected there were no inside meters found.	
192.359(a)	Is the meter operating pressure within the allowable limits of the meter case rating?	Satisfactory
General Commer	<u></u>	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

192.365(a)	Is the service line valve upstream of the regulator or meter?	Satisfactory
General Comm	ent:	,
At all locations t	he service line valve was found upstream of the meter and regulator.	
192.365(c)	Is the service line located in a curb box or stand pipe that allows for ready operation?	Satisfactory
General Comm	ent:	•
During the inspe	ction of customer meters staff did not encounter any valves in curb boxes or in stand pipes.	
	LEAK SURVEY	Status
Category Comi	<u>nent:</u>	
Leak surveys we	ere performed in each of the following areas:	
192.723	Was a leak survey conducted using operator leak detection survey equipment and system maps?	Satisfactory
General Comm	ent:	-
The operator us prior to stating tl	ed a Southern Cross Flame Ionization Leak Detection Instrument to conduct the leak survey. The operator conduct ne leak survey. The operator used bump gas which is a preset amount of gas that the user knows to prove the instru	ed a test of the instrument ument is working properly.
192.603(b)	Was the operator's equipment calibrated as required?	Satisfactory
General Comm	ent:	•
Staff reviewed th	ne calibration date but did note make a note of it.	
	CATHODIC PROTECTION	Status
Category Comi	nent:	
	tion readings were taken in each of the following locations:	
Lake Winds Sub #327 Lynwood -	·	
#321 Lynwood -		
#315 Lynwood -		
#311 Lynwood - #29 Lake Wind		
#25 Lake Wind	1.25 volts wire	
#30 Lake Wind		
#22 Lake Wind - #20 Lake Wind I	not connected to main	
	1.28 volts extrub	
#17 Lake Wind		
#13 Lake Wind - #9 Lake Wind -		
	1.27 Voils wife	
#320 Lynwood	-1.28 volts wire	
#316 Lynwood		
#312 Lynwood #308 Lynwood		
t308 Lynwood -1.28 volts extrub t36 Lynwood -1.27 volts wire		
#36 Lynwood - #40 Lvnwood -		

#35 Lansing -1.25 volts wire

192.463(a)	Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?	Satisfactory
General Comm	ent:	
	es this section; A negative (cathodic) voltage of at least 0.85 volt, with reference to a saturated copper-copper sulfate t be made with the protective current applied, and in accordance with sections II and IV of this appendix.	es half cell. Determination of
192.465(a)	Were pipe to soil readings taken?	Satisfactory
General Comm	ent:	
Staff did not insp	pect any isolated section of mains or services during this audit.	
192.465(b)	Were rectifier installations inspected?	Not Checked
General Comm	ent:	
The parts of the	distribution inspected were not rectified.	
192.465(a)	Were isolated mains/services tested?	Not Checked
General Comm	ent:	
Staff did not insp	nect any isolated section of mains or services during this audit.	
192.465(c)	Were critical/non critical bonds tested?	Not Checked
General Comm	ent:	
There were no c	ritical/non critical bonds in the areas inspected.	
192.467(a)	Is electrical isolation provided by use of insulated meter spud, valve, union, or flange?	Satisfactory
General Comm	ent:	
The operator us	ed insulating meter spuds at the meter sets or was constructed of plastic.	
192.467(c)	Were casing installations tested for electrical isolation?	Not Checked
General Comm	ent:	
Staff did not incl	ude any casings in the audit.	
192.479(a)	Is the above ground piping coated or painted as required?	Satisfactory
General Comm	ent:	
The operator did inspection.	find some meter locations that needed some type of corrections such a painting some of these locations were alrea	ndy found prior to this
192.479(c)	Is the pipeline free of corrosion or pitting?	Satisfactory
General Comm		

	MARKING OF FACILITIES	Status
Category Comm	ent:	
Line markers were	e checked at each regulating station and all signs were found to meet the requirements of the section below.	
192.707(a)(1)	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Satisfactory
192.707(a)(2)	Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	Satisfactory
192.707(c)	Are line markers placed and maintained as close as practical over each buried main and transmission line located above ground?	Satisfactory
192.707(d)(1)	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	Satisfactory
192.707(d)(2)	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The name and phone number (including area code) of the operator where the operator can be reached at all times.	Satisfactory
	ODORIZATION OF GAS	Status
192.625(a)	Was the odor intensity level readily detectable at or below 1/5th LEL?	Satisfactory
General Comments Staff conducted a17% gas in air.	nt: n odor intensity level check at the Rochester Fire Department. Threshold performed first was .11% gas in air, next v	was the odorant test it was
192.625(f)	Was the operator's equipment calibrated as required?	Satisfactory
	nt: 38-3 Heath Odorator 5-24-12 recalibration date 5-24-13	
Cambration Date of	PRESSURE LIMITING AND REGULATING STATIONS	Status
Category Comme		
Staff inspected the	e following regulating stations: XS080, XS046, XS201, XS168, XS154, and XS111.	
192.741	Was the chart recorder calibration verified, if applicable?	Not Checked
General Comme	nt:	
Staff did not inspe	ect the chart recorders at the time of this inspection.	
192.603(b)	Were the types of regulators and pressure relief devices verified?	Not Checked

General Comme	<u>ent:</u>	
Staff did not verif	y the types of regulators or pressure relief devices at the time of this inspection.	
192.181	Were the valves associated with regulator stations/vaults visually inspected to be readily accessible?	Satisfactory
192.707(c)	Is station marked properly?	Satisfactory
General Comme	ent:	
Staff verified prop	per signage and line markers at the station locations.	
192.615	Was the MAOP of the downstream system verified?	Satisfactory
General Comme	ent:	
Staff verified this	information by asking the operator personnel in the field.	
192.739(a)	Was the most recent regulator station inspection data reviewed?	Not Checked
General Comme	ent:	
Staff did not revie	ew station data during the field inspection.	
192.739(a)	Was the set point and lockup pressure from the most recent inspection data reviewed?	Not Checked
General Comme	ent:	
Staff only did a v	isual inspection of the regulating stations.	
192.739(a)(3)	Was the set point field verified?	Not Checked
General Comme	ent:	
Staff did not field	verify the set point of the regulating stations.	
192.317(b)	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?	Satisfactory
General Comme	ent:	
All regulating sta	tions inspected were found to be protected from accidental damage by distance from the road and most had fences a	and some type barricades
192.199(d)	Did the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Satisfactory
General Comme	ent:	
All supports in th	e regulating stations were made of steel.	
192.199(e)	Did the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?	Satisfactory
General Comme	ent:	

192.199(h)	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?	Satisfactory
General Comme	ent:	
All valves found	under any type relief valve were all equipped with a locking device.	
	VALVE MAINTENANCE	Status
Determine if e	estimated number of customers affected by valve closure meets operator maximum allowed age.	
General Comme	ent:	
This information	was not determined during the audit.	
192.747(a)	Were the valves inspected accessible?	Satisfactory
General Comme	ent:	
Valves at the reg	ulating stations were inspected and found to be accessible.	
192.747(a)	Was the condition of the valve boxes inspected?	Satisfactory
192.603(b)	Are valves recorded correctly on maps and inspection forms/screens?	Not Checked
General Comme	ent:	
Staff did not revi	ew maps for the valve locations.	